

Passande skruvmejsel för olika skruvar



Maskinskruv



Raka spår

| Mejseltjocklek x mejselbredd mm | För Metrisk skruvar M | | | | För Unified skruvar UNC | | |
|------------------------------------|-----------------------|-------|-------|-------|-------------------------|----------------|----------------|
| | MCS | MSCS | MFS | MKFS | ULCS | UFS | UKFS |
| | | | | | | | |
| 0,4x2,5 | M 1,6 | M 1,6 | M 1,6 | M 1,6 | – | – | – |
| 0,5x3 (0,5x3,5) | M 2 | M 2 | M 2 | M 2 | – | – | – |
| 0,6x3,5 (0,6x4) | M 2,5 | M 2,5 | M 2,5 | M 2,5 | – | – | – |
| 0,8x4 (0,8x5,5) | M 3 | M 3 | M 3 | M 3 | Nr 5 | Nr 5 | Nr 5 |
| 1,0x5,5 (1,0x6,5) | M 3,5 | M 3,5 | M 3,5 | M 3,5 | Nr 6, 8 | Nr 6, 8 | Nr 6, 8 |
| 1,2x6,5 | M 4 | M 4 | M 4 | M 4 | Nr 10, 12 | Nr 10, 12 | Nr 10, 12 |
| 1,2x8 | M 5 | M 5 | M 5 | M 5 | – | – | – |
| 1,6x10 | M 6 | M 6 | M 6 | M 6 | 1/4 | 1/4 | 1/4 |
| 2,0x12 (2x13) | M 8 | M 8 | M 8 | M 8 | 5/16, 3/8, 1/2 | 5/16, 3/8, 1/2 | 5/16, 3/8, 1/2 |
| 2,5x14 (2,5x16) | M 10 | M 10 | M 10 | M 10 | 5/8, 3/4 | 5/8, 3/4 | 5/8, 3/4 |

Mejseldimensioner inom parentes avser äldre standard.



Kryss-spår (Phillips och Pozidriv/Supadriv)

| Kryss-spår nr | För Metrisk skruvar M | | | För Unified skruvar UNC | | |
|---------------|-----------------------|---------------------|---------------------|-------------------------------|-------------------------------|-------------------------------|
| | MRX | MFX | MFKX | URX | UFX | UKFX |
| | | | | | | |
| 0 | M 1,6 M 2 | M 1,6 M 2 | M 1,6 M 2 | | | |
| 1 | M 2,5 M 3 | M 2,5 M 3 | M 2,5 M 3 | | | |
| 2 | M 3,5 M 4 M 5 | M 3,5 M 4 M 5 | M 3,5 M 4 M 5 | Nr 5 Nr 6 Nr 8 Nr 10 | Nr 5 Nr 6 Nr 8 Nr 10 | Nr 5 Nr 6 Nr 8 Nr 10 |
| 3 | M 6 | M 6 | M 6 | Nr 12 1/4 | Nr 12 1/4 | Nr 12 1/4 |
| 4 | M 8 M 10 | M 8 M 10 | M 8 M 10 | 5/16 3/8 7/16 1/2 | 5/16 3/8 7/16 1/2 | 5/16 3/8 7/16 1/2 |